

July 29<sup>th</sup> 2008

Technical Service Bulletin ..... HB-0729-08

## Curtis Drive Motor Control Boards

The Curtis control boards are programmed in the factory to meet ANSI standards and are ***model specific***.

For replacement, the following parts numbers must be used:

HB1030 manufactured prior to 2008: Part # ELEC-900  
(serial numbers 52250-53381)

HB1030 manufactured beginning in 2008 and HB1430: Part # ELEC-901  
(HB1030 serial numbers beginning with 54000;  
HB1430 serial numbers 6200-6996, 72001-current)

In the past, you might have ordered replacement control boards #ELEC-127. This part number has been replaced with model specific part numbers.

If your parts department has (unlabeled) control boards in inventory, please contact Custom Equipment, Inc. for a return tag. Boards will be returned to the factory for program verification and labeling, and we will return them to you.



### **WARNING**

FAILURE TO USE THE CORRECT CONTROL BOARD  
WILL RESULT IN A UNIT THAT DOES NOT CONFORM  
TO CURRENT ANSI SAFETY STANDARDS

### **Steve "Chappie" Chapman**

Service, Warranty, & Repair Parts Manager  
(262) 644-1300 office  
(262) 573-0396 cell

**Custom Equipment, Inc. / Hy-Brid Lifts**

[www.hybridlifts.com](http://www.hybridlifts.com)

[chappie@customequipmentlifts.com](mailto:chappie@customequipmentlifts.com)